

## REPORTS AND PUBLICATIONS by David Banks.

### Other Reports

- Misund, A., Morland, G., Brunstad, H. & Banks, D. 1991.** Kartlegging av spesialavfall i deponier og forurenset grunn - Sluttrapport [*A survey of hazardous waste disposal in landfills and contaminated soil - Final report - in Norwegian, with English summary*]. **Statens forurensningstilsyn (State Pollution Control Authority) report** 91.01. 53 pp.
- Henriksen, T., Abrahamsen, G., Banks, D., Dahl, R., Haukland, R., Lindmo, T. & Saxebøl, G. 1992.** Deponi for lavt og middels radioaktivt avfall - konsekvensutredning [*Repository for low and intermediate level radioactive waste - impact assessment - in Norwegian*]. **Statens Bygge- og Eiendoms Direktorat**, 90 pp.
- Banks, D. and others 1994.** The design of a soil and groundwater monitoring programme for xxxxxxxxx Airport. Final Report and Executive Summary. Project No. AAJCM/000CC. **Scott Wilson Kirkpatrick Report.**
- Banks, D. 1994.** Environmental acquisition audit. Cawdor Quarry, Matlock. **Scott Wilson Kirkpatrick Report.**
- Banks, D. and others 1994.** Draft final report on site investigation and contamination assessment, xxxxxxxx tar disposal lagoons, xxxxxxxx, Derbyshire. **Scott Wilson Kirkpatrick Report, in association with Aspinwall & Co.**
- Banks, D., Gustad, K. & Meholli, H. 2000.** Assessment of water and sanitation status: 15 villages in Vushtrri and Skenderaj municipalities; Mitrovice District; Kosova. **Action by Churches Together / Norwegian Church Aid**, November 2000.
- Dames & Moore 2000a.** Sub-Project 7.Hydrogeological Study of the San José Mine and Adjacent Aquifers Supplying Water to the City of Oruro: Report 1 - Risk Source Characterisation: San José Mine. **Report by Dames & Moore Norway to COMIBOL, Bolivia.**
- Dames & Moore 2000b.** Sub-Project 7.Hydrogeological Study of the San José Mine and Adjacent Aquifers Supplying Water to the City of Oruro: Report 2 - Risk Transport Pathway: Regional Hydrogeology. **Report by Dames & Moore Norway to COMIBOL, Bolivia.**
- Dames & Moore 2000c.** Sub-Project 7.Hydrogeological Study of the San José Mine and Adjacent Aquifers Supplying Water to the City of Oruro: Report 3 - Results of Field Investigations / Hydrogeochemical Interpretation. **Report by Dames & Moore Norway to COMIBOL, Bolivia.**
- Dames & Moore 2000d.** Sub-Project 7.Hydrogeological Study of the San José Mine and Adjacent Aquifers Supplying Water to the City of Oruro: Report 4 - Numerical Modelling and Risk Assessment. **Report by Dames & Moore Norway to COMIBOL, Bolivia.**
- Brown & Root / Scott Wilson 2001.** The Sherwood Sandstone aquifer of the Doncaster and Selby areas, hydrogeological review. **Report R/031/I/024, by David Banks for Brown & Root / Scott Wilson, to Yorkshire Water Services**, dated June 2001, 117 pp plus figures and appendices.
- Banks, D. 2001.** Guidelines for sustainable use of groundwater in Afghanistan (with Appendix containing recommendations for NCAAP's drought response 2001-2002). **Report dated 1/9/01 (final version) to Norwegian Church Aid, Afghanistan Program** (Peshawar/Kabul).
- Brown & Root / Scott Wilson 2002.** The Sherwood Sandstone aquifer of the Doncaster and Selby areas, environmental appraisal. **Report R/031/I/024 by Stephanie Peay, Neil Stephenson, David Banks and others for Brown & Root / Scott Wilson, to Yorkshire Water Services**, dated February 2002, 62 pp plus figures and appendices.
- Banks, D. 2002.** Water assessment mission to Afghanistan, January-February 2002. **Report for Norwegian Church Aid**, dated 26/2/02.
- Banks, D. 2002.** BTC pipeline - environmental impact assessment: hydrogeology. **Report to RSK Environment Ltd. (Helsby)**, draft issued January 2002.

*David Banks is also a Director of Holymoor Consultancy Ltd.,  
Registered as a limited company from 12/11/2008,  
Company registration number 067477725,  
Registered office: 8 Heaton Street, Chesterfield, Derbyshire, S40 3AQ, UK.*